

ASSEMBLY INSTRUCTION

TB-I2046
WINDSOR SERVING TABLE







FIG.1




FIG.2




FIG.3

Part List :

- 1 pc Top, 1 pc Legs Support, 2 pcs Legs

Assembling :

1. Prepare the top and legs (Right or left).
Then put glue around the tenon in Top and Insert legs in to the top (FIG.1)
2. Insert support leg that has been given glue on the tenon to the legs (FIG.2)
3. Then insert other legs to the top and support legs (FIG.3)
4. Insert to wood dowel on the all hole