

		Assembly Instructi	
List of Parts for Assem	nbly of		
No	Parts Description	Qty	
Α	Table Top	1	
В	Leg Support (Short) (*with Sloped and Dented Wings)	2	A
С	Leg Support (Long) (*with Sloped and Dented Wings)	2	В —
D	Table Leg	4	
E	Washers ( 8mm )	12	— a —
F	Spring Washers (8mm)	12	
G	Nuts (8mm)	12	
Н	Screws(8x40)	4	I
I	Rubber Caps (pre-installed)	4	
J	Wrench	1	


**EFG** 



## Assembly Instructions







3. First put the leg support(B&C) mark Dented and then attach the other end mark screw hole. Attach four table legs(D) to the contact Sloped Support Panel together. Affix the leg support(B&C) to the table legs with the washers(E), spring washers(F) and nuts(G)((Fig.1). (Do not over tighten). Repeat the same process for all 03 contact points of the Table Legs and the Legs Support Panels.(please note the direction of the flower pattern of leg support B&C)



4. Turn the table right side up. Adjust the preinstalled adjustable plastic feet (I) at the end of each table leg until the table is level with the groud. Securely, tighten and fasten all the nuts. Your table is ready for use.